

Iron 5649
ANNUAL SURVEYS.

23760

No. 388 Survey held at London Date July 10th to 20th 1867
on the Iron Vessel Bt "London" Master W. J. S. Hall
Tonnage 1303 Built at Newcastle When built 1862 (3 mo)
By whom built Leslie Owners W. Wood
Port belonging to London Destined Voyage Gibraltar
If Surveyed Afloat or in Dry Dock Entered dry Dock.

Last Survey, No. 5148 Port of Iron. Classed G.A.1 (C. 65) 10.66

The present Condition of the

Decks	Good where seen	Treenails Rivets	Good where seen	Windlass and Capstan	Good and sufficient where seen
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats 5	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c. good	
Lower Deck Beams & Fastenings		Keelsons		Sails	
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales		Copper paint When put on now		Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where seen.

Sighted bottom, scraped and payed with 4 coats of mixed Red Lead &c. Bored out the shaft hole; The whole of the Cement seen in the flat of Bottom in one of the amidship compartments, also at a few other places in the remainder of the compartments, and found Cement and frames &c. good where seen; She is now in good and efficient condition and fit in my opinion to remain classed G.A.1.
Committee's Minute 30th July 1867
Character assigned G.A.1 M.S.
Joseph Allen.
Certificate (if required)

No. Survey held at Date 18
on the Master
Tonnage Built at When built
By whom built Owners
Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper When put on	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways

Committee's Minute 18
Character assigned