

5672

REPORT of SURVEY for REPAIRS.

in Book. No. 29748 Survey held at Liverpool Date 13th June to 22 July 1867
 on the Iron S. "Viscata" Master Drummond
 Tonnage 1065 Built at Liverpool When built 1864-2 mo
 By whom built Port Owners A Steel
 Port belonging to Liverpool Destined Voyage San Francisco
 If Surveyed Afloat or in Dry Dock Queens dry dock & Afloat

st Survey, No. 3591 Port Iron Classed A1
64

PAIRS
 Seiling in Hold lifted all Iron & off each side
 cement repaired where found requisite, outside
 painted and coated.

Present Condition of the

Decks		Keelsons		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings	Good	Transoms, Pointers, and Crutches	Good	Boats	Good
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers	Where	Keelsons	Where	Sails	and
Sheerstrakes		Clamps and Shells		Anchors No. of	
Topsides		Ceiling		Cables	Suffr
Wales		Rudder	Seen	Hawsers and Warps	
Plank (Bottom) and Counter	Seen	Copper cement When put on	1864	Standing & Running Rigging	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. Good				

She is now in good condition and in my
 opinion may remain as Classed A1 and marked
 S S No 1. 1867

The Amount of Fee.....£ " : " : " is received by me,

Special.....2 : 2 : - 1/46

Certificate (if required) " : " : "

Committee's Minute Liverpool, 9th August 1867

Character assigned A1 - (S. S. No 1-67) - Class - 64

Will. C. Davy



© 2019
 Lloyd's Register
 Foundation

IRON44-0133

REPORT OF SURVEY FOR REPAIRS

"Viscata"
20748



© 2019

Lloyd's Register
Foundation