

5689
ANNUAL SURVEYS.

Rec 14/9/67

No. 2083 Survey held at Liverpool Date 29 Sept 1867
 on the Iron Ship Alexandria Master Kelly
 Tonnage 1352 Built at Belfast When built 1863 H.M.S.
 By whom built _____ Owners T & J Besant & Co
 Port belonging to Liverpool Destined Voyage for India
 If Surveyed Afloat or in Dry Dock London Docks

Last Survey, No. 5226 Port of More Classed A1
 (SSN 1.66) 12.66

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings <u>Where</u>	Keelsons <u>Where</u>	Sails <u>Where</u>
Planksheers _____	Clamps and Shelves _____	Anchors No. of _____
Sheerstrakes _____	Ceiling _____	Cables _____
Topsides _____	Rudder <u>Seen</u>	Hawsers and Warps _____
Wales _____	Copper <u>Cemented</u> When put on <u>When built</u>	Standing & Running Rigging <u>Seen</u>
Plank (Bottom) and Counter <u>Seen</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good Where Seen

This ship is in good and efficient condition eligible to remain as classed A1

Committee's Minute Liverpool 13th September 1867
 Character assigned A1 - Com-43

H. V. Munford

Certificate (if required)

No. 382 Survey held at Liverpool Date 2nd Sept 1867
 on the Iron Ship Bremchard Wyckham Master Scott
 Tonnage 1257 Built at Liverpool When built 1864 H.M.S.
 By whom built _____ Owners Bombay Shipping Co.
 Port belonging to Bombay Destined Voyage for India
 If Surveyed Afloat or in Dry Dock London Docks

Last Survey, No. 5152 Port of More Classed A1
 18.66

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Keelsons <u>Where</u>	Sails <u>Where</u>
Planksheers <u>Where</u>	Clamps and Shelves _____	Anchors No. of _____
Sheerstrakes _____	Ceiling _____	Cables _____
Topsides _____	Rudder <u>new painted</u> <u>Seen</u>	Hawsers and Warps _____
Wales _____	Copper <u>Cemented</u> When put on <u>When built</u>	Standing & Running Rigging <u>Seen</u>
Plank (Bottom) and Counter <u>Seen</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good Where Seen

This ship is in good and efficient condition eligible to remain as classed A1

Committee's Minute Liverpool 13th September 1867
 Character assigned A1 - Com-44

H. V. Munford
 Certificate (if required).

Memoranda

Richard Wood

20831



© 2019

Lloyd's Register
Foundation