

# ANNUAL SURVEYS.

No. 20808 Survey held at Liverpool Date 19<sup>th</sup> to 28<sup>th</sup> Aug 1867  
 on the Iron Ship Dharmar Master White  
 Tonnage 1294 Built at Belfast When built 1864 9<sup>th</sup>  
 By whom built \_\_\_\_\_ Owners Iron Ship Co. (Limp.)  
 Port belonging to Bombay Destined Voyage for India  
 If Surveyed Afloat or in Dry Dock Clarence Graving Dock No 1

Last Survey, No. 4624 Port of Iron Classed A1

present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Keelsons _____	Sails _____
Planksheers <u>Where</u>	Clamps and Shelves <u>Where</u>	Anchors No. of _____
Sheerstrakes _____	Ceiling _____	Cables _____
Topsides _____	Rudder _____	Hawsers and Warps _____
Wales _____	Copper <u>See</u> When put on <u>When built</u>	Standing & Running Rigging <u>See</u>
Plank (Bottom) and Counter <u>See</u>	Bottom cleaned & coated <u>Good</u>	
General Observations and Opinion,	Caulking of Bottom, Deck, and Waterways <u>Good</u>	

This ship is in good and efficient condition eligible to remain as classed A1

Committee's Minute Liverpool 2<sup>nd</sup> September 1867

Character assigned A1

H. Munro

Certificate (if required)

No. \_\_\_\_\_ Survey held at Liverpool Date 19<sup>th</sup> to 24<sup>th</sup> Aug 1867  
 on the Iron Ship Oberon Master H. Smith  
 Tonnage 1185 Built at P. Glasgow When built 1864 2<sup>nd</sup>  
 By whom built \_\_\_\_\_ Owners Bourne  
 Port belonging to Liverpool Destined Voyage for India  
 If Surveyed Afloat or in Dry Dock Clarence Graving Dock No 1

Last Survey, No. 4170 Port of Iron Classed A1

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings <u>Where</u>	Keelsons <u>Where</u>	Sails _____
Planksheers _____	Clamps and Shelves _____	Anchors No. of _____
Sheerstrakes _____	Ceiling _____	Cables _____
Topsides _____	Rudder <u>See</u>	Hawsers and Warps _____
Wales _____	Copper <u>See</u> When put on <u>When built</u>	Standing & Running Rigging <u>See</u>
Plank (Bottom) and Counter <u>See</u>	Bottom cleaned & coated <u>Good</u>	
General Observations and Opinion,	Caulking of Bottom, Deck, and Waterways <u>Good</u>	

This ship is now in good and efficient condition eligible to remain as classed A1

Committee's Minute Liverpool 2<sup>nd</sup> September 1867

Character assigned A1

H. Munro

Certificate (if required).



"Tharwar"  
-20808  
"Oberan"



© 2019

Lloyd's Register  
Foundation