

5746

ANNUAL SURVEYS.

28004

Nov 12. 94

No. 176 Survey held at London Date Aug 16th 31 1867
 on the Iron Ship "White Eagle" Master Andrew
 Tonnage 878 Built at Glasgow When built 1855
 By whom built _____ Owners Bilbe
 Port belonging to London Destined Voyage Lardiff
 If Surveyed Afloat or in Dry Dock Union Dry Dock & West India Dock

Last Survey, No. 4280 Port of Iron Classed A.1
Ch. 64.5
(S. 65)

The present Condition of the		Treenails <u>Rivets</u>		Windlass and Capstan	
Decks		Breasthooks and Stemson		Pumps	
Waterways		Transoms, Pointers, and Crutches	<u>good</u>	Boats	<u>good</u>
Comings	<u>good</u>	Timbers of the Frame at the Openings		Masts, Yards, &c.	
Upper Deck Beams & Fastenings		Ditto ditto at other places	<u>where</u>	Sails	<u>where</u>
Lower Deck Beams & Fastenings	<u>where</u>	Keelsons		Anchors No. of <u>3 B 15 26</u>	
Planksheers <u>Scraped & painted</u>		Clamps and Shelves		Cables	
Sheerstrakes <u>4 4</u>		Ceiling	<u>seen</u>	Hawsers and Warps	<u>seen</u>
Topsides <u>4 4</u>	<u>seen</u>	Rudder		Standing & Running Rigging	
Wales <u>4 4</u>		Copper <u>Paint</u> When put on <u>now</u>			
Plank (Bottom) and Counter <u>Scraped & painted</u>					

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where seen
Now done, the bottom scraped and painted with three coats (Zinc & Tallin)
rigging stripped and overhauled, new fore topmast, and a bower anchor now
supplied 25^{cent} 3^{cent} 20 ex stock tested to 25^{cent} 6^{cent} at Poplar Proving House assigned
by J.M. Gladstone 30th Decr/65 No. 1459. She is now in good condition
fit in our opinion to remain as classed A.1.
 Committee's Minute September 1867
 Character assigned Cont^d 5 A 1 M.S. J. J. Smith
 Certificate (if required)

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the		Treenails		Windlass and Capstan	
Decks		Breasthooks and Stemson		Pumps	
Waterways		Transoms, Pointers, and Crutches		Boats	
Comings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Upper Deck Beams & Fastenings		Ditto ditto at other places		Sails	
Lower Deck Beams & Fastenings		Keelsons		Anchors No. of	
Planksheers		Clamps and Shelves		Cables	
Sheerstrakes		Ceiling		Hawsers and Warps	
Topsides		Rudder		Standing & Running Rigging	
Wales		Copper _____ When put on _____			
Plank (Bottom) and Counter					

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways

Committee's Minute _____ 18____
 Character assigned _____