

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 21 Survey held at London Date Sept^r 11th 1867
 on the W^m Palestine (Iron) Master J. Parke
 Tonnage 608 Built at Belfast When built 1863
 By whom built _____ Owners W. H. Lindall
 Port belonging to Scarbro Destined Voyage Colombo
 If Surveyed Afloat or in Dry Dock Carters dock & West India Dock

Last Survey, No. 5151 Port Iron. Classed A 1
 10-66

REPAIRS

Seven iron bulwark stantions renewed with angle iron $4\frac{1}{2} \times 3 \times \frac{7}{16}$ and scarphed onto the main frame — two strakes of hatches removed on both sides in the flat and the cement and bottom found in good condition — The bottom outside repainted with two coats of line and one of Tallow.

Present Condition of the

Decks	Freemasts	Roofs	Windlass and Capstan
Waterways	Breasthooks and Stemson		Pumps
Comings	Transoms, Pointers, and Crutches		Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings		Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places		Condition, how ascertained
Planksheers	Keelsons		Sails
Sheerstrakes	Clamps and Shelves		Anchors No. of
Topsides	Ceiling		Cables
Wales	Rudder		Hawsers and Warps
Plank (Bottom) and Counter	Copper	When put on	Standing & Running Rigging

General Observations and Opinion, _____ Caulking of Bottom, Deck, & Waterways. Good where seen

This vessel is eligible to remain as classed and be marked S.S. No 1-67

The Amount of Fee.....£ — : — : is received by me,

Special..... 1 : 1 : —

Certificate (if required) :

Committee's Minute 20th September 1867

Character assigned A 1



© 2019

Lloyd's Register Foundation

IRON 441-0222