

27/9/67

5788 ANNUAL SURVEYS.

No. 20849 Survey held at Liverpool Date 17th to 25th Sept 1867
 on the iron vessel "Demetrius" Master Byrne
 Tonnage 527 Built at Martlepool When built 1856
 By whom built J Owners Martali & Co
 Port belonging to London Destined Voyage Mediterranean
 If Surveyed Afloat or in Dry Dock Mercantile Gearing Dock and Afloat

Last Survey, No. 4659 Port of Iron. Classed B1
1.5.66 1.66

The present Condition of the		
Decks	Planks <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stanchion	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Stuffs	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Cen</u> When put on <u>1856</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways where seen good
Rudder pintle repaired. Bottom coated with M. J. Jarvis' Composition.
Ship in good and efficient condition and in my opinion eligible
to remain as classed B1.

Committee's Minute Liverpool 4th October 1867

Character assigned A1 - Cen. 1.5.66

J. H. Turner

Certificate (if required).

No. 486 Survey held at Liverpool Date 16th to 25th Sept 1867
 on the iron ship "British Consul" Master Carter
 Tonnage 1267 Built at Liverpool When built 1856 - 8 mo
 By whom built Royden Owners British Ship Prop. Comp.
 Port belonging to Liverpool Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Mercantile Gearing Dock and Afloat

Last Survey, No. 5141 Port of Iron. Classed A1
10.66

The present Condition of the		
Decks	Planks <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stanchion	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Stuffs	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Cen</u> When put on <u>1856</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways where seen good
Bottom cleaned and coated with Paint and Gallon.
Ship in good and efficient condition and in my opinion eligible
to remain as classed B1.

Committee's Minute Liverpool 4th October 1867

Character assigned A1 - Cen. 10.66

J. H. Turner
 Lloyd's Register Foundation
 Certificate (if required).

THE LLOYD'S REGISTER

"Amretrint"
"Puhoh Conrub"



© 2019

Lloyd's Register
Foundation