

ANNUAL SURVEYS.

Rec 23/10/67

No. 20910 Survey held at Liverpool Date 3rd 16th October 1867
 on the Iron Ship Bayard Master Jackson
 Tonnage 1319 Built at Liverpool When built 1864 3 mo
 By whom built _____ Owners L. Young & Co.
 Port belonging to Liverpool Destined Voyage Lin Calcutta
 If Surveyed Afloat or in Dry Dock Sandon Gearing Dock No 6

Last Survey, No. 4447 Port of Iron. Classed A1
 6-65-

The present Condition of the

Decks <u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson		Pumps
Comings	Transoms, Pointers, and Crutches		Boats <u>Good</u>
Upper Deck Beams & Fastenings	Timbers of the Frame		Masts, Yards, &c.
Lower Deck Beams & Fastenings <u>Where</u>	Keelsons	<u>Where</u>	Sails <u>Sufficient</u>
Planksheers	Clamps and Shelves		Anchors No. of
Sheerstrakes	Ceiling		Cables <u>Where</u>
Topsides	Rudder		Hawsers and Warps
Wales	Bottom Coated <u>Seen</u>		Standing & Running Rigging <u>Seen</u>
Plank (Bottom) and Counter <u>Seen</u>	Copper Cemented When put on <u>Seen</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good Where Seen

*This ship is in good and efficient condition.
 eligible to remain as classed A1*

Committee's Minute Liverpool 22nd October 1867

Character assigned A1

Certificate (if required)

No. 133 Survey held at Liverpool Date 3rd 16th Oct. 1867
 on the Iron Ship Hartford Master Courtesy
 Tonnage 1224 Built at Glasgow When built 1864 3 mo
 By whom built _____ Owners W. Rowe
 Port belonging to Liverpool Destined Voyage Lin Bombay
 If Surveyed Afloat or in Dry Dock Clarence Gearing Dock No 3

Last Survey, No. 5070 Port of Iron. Classed 12A1
 9-66

The present Condition of the

Decks <u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson		Pumps
Comings	Transoms, Pointers, and Crutches		Boats <u>Good</u>
Upper Deck Beams & Fastenings	Timbers of the Frame		Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	<u>Where</u>	Sails <u>Sufficient</u>
Planksheers <u>Where</u>	Clamps and Shelves		Anchors No. of
Sheerstrakes	Ceiling		Cables <u>Where</u>
Topsides	Rudder		Hawsers and Warps
Wales	Bottom Coated <u>Seen</u>		Standing & Running Rigging <u>Seen</u>
Plank (Bottom) and Counter <u>Seen</u>	Copper Cemented When put on <u>Seen</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good Where Examined

*This ship is in good and efficient condition.
 eligible to remain as classed 12A1*

Committee's Minute Liverpool 22nd October 1867

Character assigned 12A1

Certificate (if required)

IRON441-0271

*Bayard
-20910
Hartfell*



© 2019

Lloyd's Register
Foundation