

5856

2875

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 900 Survey held at London Date Nov 5<sup>th</sup> 18 67  
 on the S. Millwall Master Smith  
 Tonnage 1175 Built at London When built 1863  
 By whom built Millwall Iron Works Co. Owners Morre & Co  
 Port belonging to Liverpool Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock in Pontoon and afloat Victoria Dock

Last Survey, No. 5178 Port Lon. Classed A1  
11. 66

## REPAIRS

Lifted timber boards and ceiling at bilges equal to a stake for examination of plating, frames, cement &c., all of which were found to be in good condition, and the cement adhering in a satisfactory manner.

Scraped and painted bottom with two coats of Zinc paint and one of tallow.

## Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	"	Rivets	"	Pumps	"
Comings	"	Breasthooks and Stemson	"	Boats	"
Upper Deck Beams & Fastenings	"	Transoms, Pointers, and Crutches	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Condition, how ascertained	<u>from inquiry &amp; as seen from deck</u>
Planksheers	"	Ditto Ditto at other places	"	Sails	"
Sheerstrakes	"	Keelsons	"	Anchors No. of	<u>3 B, 1 S, 2 K</u>
Topsides	"	Clamps and Shelves	"	Cables	"
Wales	"	Ceiling	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Rudder	"	Standing & Running Rigging	"
General Observations and Opinion,		Copper	<u>When put on</u>		
		Caulking of Bottom, Deck, & Waterways.	<u>where seen</u>		

Is now in good and efficient condition and in my opinion fit to remain as classed and be marked S.S. No. 1. 67.

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : 0

Certificate (if required) : :

Committee's Minute 19<sup>th</sup> November 18 67

Character assigned A

S.S. No. 1. 67



© 2019

Lloyd's Register  
Foundation

IRON441-0318