

# ANNUAL SURVEYS.

3890  
2877#

No. 221 Survey held at London Date Nov 16<sup>th</sup> 18 67  
on the S.S. "Florence" Master Thompson  
Tonnage 797 Built at Newcastle When built 1866  
By whom built Bambridge Owners S. Bourley  
Port belonging to Sunderland Destined Voyage  
If Surveyed Afloat or in Dry Dock On Pontoons Victoria Dock

Last Survey, No. 5746 Port of Iron. Classed B1 3.67

The present Condition of the

Decks	Good	Greenails	Rivets	Good	Windlass and Capstan	Good
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Sails	"
Planksheers	"	Keelsons	"	"	Anchors No. of	3 B, 1 S, 2 K
Sheerstrakes	"	Clamps and Shelves	"	"	Cables	"
Topsides	"	Ceiling	"	"	Hawsers and Warps	"
Wales	"	Rudder	"	"	Standing & Running Rigging	"
Plank (Bottom) and Counter	"	Copper	When put on	"		

Painted with 2 coats of R.W. lead  
General Observations and Opinion, Caulking of Bottom, Deck, and Waterways where seen Good

Is now in good and efficient condition and in my opinion eligible to remain as classed.

Committee's Minute 29<sup>th</sup> Nov 18 67  
Character assigned B1

John Maxwell

Certificate (if required)

141 No. Survey held at London Date Nov 23<sup>rd</sup> 18 67  
on the S.S. "Onward" Master Luckie  
Tonnage 783 Built at Sunderland When built 1865  
By whom built Oswald Owners J. Gunn  
Port belonging to London Destined Voyage New York  
If Surveyed Afloat or in Dry Dock On Pontoons Victoria Dock & afloat

Last Survey, No. 4347 Port of Iron. Classed B1 10.65

The present Condition of the

Decks	Good	Greenails	Rivets	Good	Windlass and Capstan	Good
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Sails	"
Planksheers	"	Keelsons	"	"	Anchors No. of	3 B, 1 S, 2 K
Sheerstrakes	"	Clamps and Shelves	"	"	Cables	"
Topsides	"	Ceiling	"	"	Hawsers and Warps	"
Wales	"	Rudder	"	"	Standing & Running Rigging	"
Plank (Bottom) and Counter	"	Copper	When put on	"		

Painted with 2 coats of Redd's paint  
General Observations and Opinion, Caulking of Bottom, Deck, and Waterways where seen Good

Is now in good and efficient condition and in my opinion eligible to remain as classed.

Committee's Minute 29<sup>th</sup> Nov 18 67  
Character assigned B1

John Maxwell

Certificate (if required).

IRON441-0342