

# ANNUAL SURVEYS.

5895  
28803  
No. 10 on the S. S. Leith Survey held at London Date November 23<sup>rd</sup> 1864  
Master Barnetson  
Tonnage 1408 Built at P. Glasgow When built 1864  
By whom built Blackwood Owners P. Mc Gregor  
Port belonging to Leith Destined Voyage Mediterranean  
If Surveyed Afloat or in Dry Dock on Pontoons & Victoria Dock

Last Survey, No. 5567 Port of Leith Classed A1  
7.64

The present Condition of the Good

Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Keelsons	"	Sails	"
Planksheers	"	Clamps and Shelves	"	Anchors No. of	<u>3 B, 1 S, 2 K.</u>
Sheerstrakes	"	Ceiling	"	Cables	"
Topsides	"	Rudder	"	Hawsers and Warps	"
Wales	"	Copper	"	Standing & Running Rigging	"

Blank (Bottom) and Counter Painted bottom with 2 coats of paint  
General Observations and Opinion, Caulking of Bottom, Deck, and Waterways where seen Good

Is now in good and efficient condition and in my opinion eligible to remain as classed.

Committee's Minute 3<sup>rd</sup> December 1864  
Character assigned A1 MS

John Maxwell

Certificate (if required)

288 No. 288 on the S. S. Bianca Survey held at London Date November 30<sup>th</sup> 1864  
Master Richardson  
Tonnage 1387 Built at Liverpool When built 1862  
By whom built Lawrence Owners Moore & Co  
Port belonging to Liverpool Destined Voyage Calcutta  
If Surveyed Afloat or in Dry Dock in Thames Iron Works Dock & East India Dock

Last Survey, No. 5218 Port of Leith Classed A1  
S.S. No. 1-65 12.66

The present Condition of the Good

Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Keelsons	"	Sails	"
Planksheers	"	Clamps and Shelves	"	Anchors No. of	<u>3 B, 1 S, 2 K.</u>
Sheerstrakes	"	Ceiling	"	Cables	"
Topsides	"	Rudder	"	Hawsers and Warps	"
Wales	"	Copper	"	Standing & Running Rigging	"

Plank (Bottom) and Counter Painted bottom with 2 coats of paint  
General Observations and Opinion, Caulking of Bottom, Deck, and Waterways where seen good

Is now in good and efficient condition and in my opinion eligible to remain as classed.

Committee's Minute 3<sup>rd</sup> December 1864  
Character assigned A1 MS

John Maxwell

Certificate (if required).