

5905

# REPORT of SURVEY for REPAIRS.

No. in  
Reg. Book. **No.** 10459 Survey held at Newcastle Date 24<sup>th</sup> Oct<sup>r</sup> 1867  
101 on the S.S. "Belvidere" Master H. Fleck  
Tonnage 596 Built at Newcastle When built 1864  
By whom built Richardson Owners Sobling &c  
Port belonging to Newcastle Destined Voyage Home  
If Surveyed Afloat or in Dry Dock Willington Quay

Last Survey, No. 4622 Port Iron Classified A.1.  
1.66.

REPAIRS now done:

The boiler lifted, the bearers, floor plates &c. cleaned and painted. Cement examined by chipping and found satisfactory.  
A new boiler fitted, deck in way of some re-laid and caulked.  
This vessel will be placed on a slip for triennial survey, at the earliest opportunity.

Present Condition of the

Decks	<u>Good</u>	Rivets Treenails	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	<u>When</u>	Ditto Ditto at other places	<u>When</u>	Condition, how ascertained	<u>and</u>
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder	<u>Seen</u>	Hawsers and Warps	
Plating Plank (Bottom) and Counter	<u>Seen</u>	Copper	When put on	Standing & Running Rigging	<u>Sufficient</u>

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good when seen

This vessel is in good and efficient condition, and eligible, in my opinion, to remain as Classed.

The Amount of Fee.....£ 4 : 4 : 4 is received by me, A. Harding

Special..... 1 : 1 : 1

Certificate (if required) .....

Committee's Minute 13<sup>th</sup> December 1867

Character assigned A.1.



© 2019

Lloyd's Register  
Foundation

IRON44-0358