

5918

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 21000** Survey held at Liverpool Date 11<sup>th</sup> to 21<sup>st</sup> Decr 1867  
 on the Iron S. "Ragpore" Master Downing  
 Tonnage 1198 Built at Glasgow When built 1863-9mo  
 By whom built Barclay Owners H. Rome  
 Port belonging to Liverpool Destined Voyage Bombay  
 If Surveyed Afloat or in Dry Dock Brunswick dry dock Afloat

Last Survey, No. 48213 Port Iron Classed 12A1  
 66

## REPAIRS

Bottom cleaned and coated. ceiling of flat lifted also one length of ceiling at the bilge ~~and~~ on each side plating. cement coating is found good

## Present Condition of the

Decks	<u>Good</u>	Ironails	<u>Rivets</u>	Windlass and Capstan	
Waterways	<u>"</u>	Breasthooks and Stenson		Pumps	
Comings	<u>"</u>	Transoms, Pointers, and Crutches	<u>where</u>	Boats	<u>Good</u>
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	<u>where</u>	Ditto Ditto at other places	<u>seen</u>	Condition, how ascertained	<u>and</u>
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shells	<u>Good</u>	Anchors No. of	
Topsides	<u>seen</u>	Ceiling		Cables	<u>Suff.</u>
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper	<u>Cement</u> When put on <u>1863</u>	Standing & Running Rigging	
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways.	<u>Good</u>		

She is now in good condition and in my opinion may in accordance with owner's desire be classed A1 and marked S.S. No 1-67

The Amount of Fee.....£ " : " : " is received by me,

Special.....2 : 2 : — 2/12/67

Certificate (if required) ... : 5 : "

Committee's Minute Liverpool 6<sup>th</sup> December 1867

Character assigned A1 S.S. No 1-67

Chm-63



© 2019

Lloyd's Register Foundation

IRON 44-0371



"Lagfene 21000-

© 2019

Lloyd's Register  
Foundation