

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 335 Survey held at London Date Nov. 30 to Jan 1 1868
 on the Iron Ship "Sea Queen" Master Flemingham
 Tonnage 873 Built at Glasgow When built 1858
 By whom built Stephen Owners Allan
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Simkirk Dry Dock & East India Dock

Last Survey, No. 4260 Port Iron. Classed 12 A. 1
 (t. s. 657-65)

REPAIRS now done,

The outside surface of the plating scraped and painted, the bottom with two coats of Zinc and two of Bell's Patent - and the inside scraped and painted from the upper deck stringer to the close ceiling with white Zinc -

Present Condition of the

Decks <u>pieced</u>	} <u>good</u>	Treenails Rivets	} <u>good</u>	Windlass and Capstan	} <u>good</u>
Waterways		Breasthooks and Stenson		Pumps	
Comings	} <u>where</u>	Transoms, Pointers, and Crutches	} <u>where</u>	Boats <u>three</u>	} <u>seen</u>
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>where</u>	Ditto Ditto at other places	} <u>where</u>	Condition, how ascertained <u>by inquiry & inspection</u>	} <u>good</u>
Planksheers <u>painted</u>		Keelsons		Sails	
Sheerstrakes	} <u>seen</u>	Clamps and Shelves	} <u>seen</u>	Anchors No. of <u>3 B. 1 S. 2 K</u>	} <u>and</u>
Topsides		Ceiling		Cables	
Wales	} <u>seen</u>	Rudder	} <u>seen</u>	Hawsers and Warps	} <u>sufficient</u>
Plank (Bottom) and Counter <u>painted</u>		Copper Paint When put on <u>now</u>		Standing & Running Rigging	

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. good where seen

She is now in good and efficient condition fit in our opinion to remain as classed

12 A. 1.

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute up to January 18 68

Character assigned 12 A. 1 AMPS

H. Mornick
 © 2019
 Lloyd's Register Foundation

IRON441-0397