

# ANNUAL SURVEYS.

6000

*Register*

No. 46 on the S.S. "Venetia" Survey held at London Date Feb 7<sup>th</sup> 18 68  
 Tonnage 755 Built at Newcastle Master R. May  
 By whom built Mitchell Owners Ocean S. N. Co  
 Port belonging to London Destined Voyage Lardiff  
 If Surveyed Afloat or in Dry Dock on Pontoons & Victoria Dock

Last Survey, No. 5670 Port of Iron S.S. No. 1. 67 Classed A1  
7.67

The present Condition of the

Decks <u>where seen Good</u>	Treenails <u>Rwets where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of <u>3 B, 1 S, 2 K</u>
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>When put on</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways where seen Good

Scraped, and painted bottom with two coats of Line paint and one of tallow.  
 Is now in good and efficient condition and in my opinion eligible to  
 remain as classed.

Committee's Minute 4<sup>th</sup> February 18 68

Character assigned A / WAS

*John Maxwell*

Certificate (if required)

No. 246 on the S.S. "Savoir Faire" Survey held at London Date Jan 29<sup>th</sup> 18 68  
 Tonnage 1396 Built at Liverpool Master Harbon  
 By whom built Rogden Owners Fletcher & Co  
 Port belonging to Liverpool Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock on Pontoons Victoria dock & East India Dock.

Last Survey, No. 5309 Port of Iron S.S. No. 1. 66. Classed A1  
2.67

The present Condition of the

Decks <u>where seen Good</u>	Treenails <u>where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of <u>3 B, 1 S, 2 K</u>
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>When put on</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways where seen Good

Scraped, and painted bottom with two coats of Line paint and one of tallow.  
 Is now in good and efficient condition and in my opinion eligible to remain  
 as classed.

Committee's Minute 4<sup>th</sup> February 18 68

Character assigned A / WAS

*John Maxwell*

Certificate (if required).

IRON441-0452