

16/68

6010

ANNUAL SURVEYS.

No. 2403 Survey held at Liverpool Date 18th 2nd Jan 1868
 on the Iron S. Landahar Master C. Mossop
 Tonnage 1418 Built at Belfast When built 1866-5 mo
 By whom built Harland Owners J. & S. Brocklebank
 Port belonging to Liverpool Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Lucius dry dock

Last Survey, No. 4798 Port of Iron. Classed A1
66

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stenson

Transoms, ~~Pointers~~, and Crutches

Timbers of the Frame

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper ~~Cement~~ When put on

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good

Bottom cleaned & coated. She appears in good condition and in my opinion may continue as classed

Committee's Minute Liverpool 18th February 1868Character assigned A1

Certificate (if required)

No. 5455 Survey held at Liverpool Date 30th Dec^r / 14th Jan 1868
 on the Iron S. "Leta" Master Walters
 Tonnage 734 Built at Glasgow When built 1865-8 mo
 By whom built Stephen Owners Bath &
 Port belonging to Swansea Destined Voyage Valparaiso
 If Surveyed Afloat or in Dry Dock Mercurian dry dock & afloat

Last Survey, No. 5455 Port of Iron.Classed A1
67

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stenson

Transoms, ~~Pointers~~, and Crutches

Timbers of the Frame

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper ~~Cement~~ When put on 1865

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good

Bottom cleaned and coated she appears in good condition and in my opinion may continue as classed

Committee's Minute Liverpool 18th February 1868Character assigned A1

Certificate (if required).

IRON441-0467

"Candahari"
21.10.52
"Zeta"



© 2019

Lloyd's Register
Foundation