

16/68

6010

## ANNUAL SURVEYS.

No. 2403 Survey held at Liverpool Date 18<sup>th</sup> 2<sup>nd</sup> Jan 1868  
 on the Iron S. Landahar Master C. Mossop  
 Tonnage 1418 Built at Belfast When built 1866-5 mo  
 By whom built Harland Owners J. & S. Brocklebank  
 Port belonging to Liverpool Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Lucius dry dock

Last Survey, No. 4798 Port of Iron. Classed A1  
66

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams &amp; Fastenings

Lower Deck Beams &amp; Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stenson

Transoms, ~~Pointers~~, and Crutches

Timbers of the Frame

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper ~~Reported not~~ Cemented When put on

Caulking of Bottom, Deck, and Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &amp;c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing &amp; Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Bottom cleaned & coated. She appears in good condition and in my opinion may continue as classed

Committee's Minute

Liverpool 18<sup>th</sup> February 1868

Character assigned

A1

Certificate (if required)

No. 5455 Survey held at Liverpool Date 30<sup>th</sup> Dec<sup>r</sup> / 14<sup>th</sup> Jan 1868  
 on the Iron S. "Leta" Master Walters  
 Tonnage 734 Built at Glasgow When built 1865-8 mo  
 By whom built Stephen Owners Bath &  
 Port belonging to Swansea Destined Voyage Valparaiso  
 If Surveyed Afloat or in Dry Dock Mercurian dry dock & afloat

Last Survey, No. 5455 Port of Iron. Classed A1  
67

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams &amp; Fastenings

Lower Deck Beams &amp; Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stenson

Transoms, ~~Pointers~~, and Crutches

Timbers of the Frame

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper ~~Reported not~~ Cemented When put on 1865

Caulking of Bottom, Deck, and Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &amp;c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing &amp; Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Bottom cleaned and coated she appears in good condition and in my opinion may continue as classed

Committee's Minute

Liverpool 18<sup>th</sup> February 1868

Character assigned

A1

Certificate (if required).

IRON441-0467



"Candahari"  
21.10.52  
"Zeta"



© 2019

Lloyd's Register  
Foundation