

6029

10157

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 10493** Survey held at Swansea Date 30th January 1868
421 on the S.S. "John Liddell" Master
Tonnage 699 built at Newcastle When built 1863
By whom built Mitchell & Co Owners J. Shaker (Arthur Pringle)
Port belonging to London Destined Voyage
☒ Surveyed Afloat ☐ in Dry Dock Willington Quay

Last Survey, No. 9977 4034 Port Newcastle Classed O.A.I.
REPAIRS now done: 3.66-

The survey of this vessel in accordance with the Rules for Iron vessels built and classed for periods of years, has now been commenced, the Fore and Main hold cleaned and painted, the Owner having now determined to give the vessel a new boiler, wishes the survey to be completed when the boiler is ready to be put on board -
I attach a letter received from the Owner on the subject.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.	

This vessel should have been surveyed in 1866, the Owner having now declined to complete the survey, I beg to leave the continuance of class to the Committee.

The Amount of Fee.....£ : : is received by me, A. Harding
Special..... : :
Certificate (if required) : :

Committee's Minute 4th February 1868
14th

Character assigned deferred
write to owner
notice to owner
14/2/68

Deposited was
14.2.68
Lloyd's Register
Foundation

IRON/441-0479