

ANNUAL SURVEYS.

Rec 27/2/68

No. 3841 Survey held at Hull Date 26th February 1868
 on the Iron Steamer "Viceroy" Master Lighton
 Tonnage 823 Built at Sunderland When built 1862
 By whom built Oswald Owners Gee & Co
 Port belonging to Hull Destined Voyage _____
 If Surveyed Afloat or in Dry Dock in Sup. Cables Slip-way & afloat in Prince Dock

Last Survey, No. 5323 Port of Gron. Classed 9 A 1
(15 66) 2. 67

The present Condition of the

Decks	<u>Good when seen</u>	Freeboards <u>None</u>	<u>Good when seen</u>	Windlass and Capstan	<u>Good when seen</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places		Sails	
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter		Copper		When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Now done Bottom cleaned & coated with Tar & Black Lead
Is eligible in my opinion & remain as classed

Committee's Minute 28th February 1868

Character assigned 9 A 1 was

M Davidson

Certificate (if required).

No. _____ Survey held at Hull Date 21st July 1868
 on the Iron Steamer "Sea Horse" Master Richie
 Tonnage 493 Built at Hull When built 1856
 By whom built 335 Owners Ringrose
 Port belonging to Hull Destined Voyage Rotterdam
 If Surveyed Afloat or in Dry Dock in Southend dry Dock

Last Survey, No. 5359 Port of Gron. Classed 12 A 1
25 65 3. 67

The present Condition of the

Decks	<u>Good when seen</u>	Freeboards <u>None</u>	<u>Good when seen</u>	Windlass and Capstan	<u>Good when seen</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places		Sails	
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter		Copper		When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Now done Bottom cleaned & coated with Tar & paint. Several
Butts at Bilge filled & caulked Is eligible in my opinion
Remain as classed

Committee's Minute 28th February 1868

Character assigned 12 A 1 was

M Davidson

Certificate (if required).

IRON 1442-0030