

6082
ANNUAL SURVEYS.

Rec 16/3/68
Supp. No. 90 Survey held at Antwerp Date March 18 68
on the iron screw Steamer Fanny David Master Hunter
Tonnage 1117 Built at Newcastle When built 1864
By whom built Marshall Owners David & Co
Port belonging to Antwerp Destined Voyage Black Sea
If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. <u>5527</u> Port of <u>Mon.</u>		Classed <u>A 1</u>
The present Condition of the <u>Ship is good</u>		
Decks <u>good</u>	Treenails <u>Rivets</u> <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Anchors No. of <u>6</u> <u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>Composition</u> When put on <u>Nov</u>	
General Observations and Opinion, <u>Caulking of Bottom, Deck, and Waterways good</u> <u>Scraped from keel outside upwards to light mark examined Rivets and plating in general</u> <u>found all in good Condition, repainted with Composition under Water and red & black upwards</u> <u>examined Cables, Windlass, Comings and all dubfastings found all in good Condition</u> <u>and are of opinion this vessel is fit to continue as Classed A 1.</u>		
Committee's Minute <u>17th March</u> 18 <u>68</u>		
Character assigned <u>A 1</u> <u>was</u>		
Certificate (if required)		

No. _____ Survey held at _____ Date _____ 18 _____
on the _____ Master _____
Tonnage _____ Built at _____ When built _____
By whom built _____ Owners _____
Port belonging to _____ Destined Voyage _____
If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____		Classed _____
The present Condition of the		
Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors No. of _____
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	
General Observations and Opinion, <u>Caulking of Bottom, Deck, and Waterways</u>		
Committee's Minute _____ 18 _____		
Character assigned _____		
Certificate (if required).		



© 2019

Lloyd's Register
Foundation

IRON 442-0052