

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 21150** Survey held at Liverpool Date 25th Jan to 23rd Feb 1868
 on the Iron S. "Hamilla Mitchell" Master Brauscombe
 Tonnage 958 built at Dumbarton When built 1864-4 mo
 By whom built Rankin Owners J. Mitchell
 Port belonging to Glasgow Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Speculaneam dry dock Afloat

Last Survey, No. 4776 Port Iron. Classed 12 A 1 66

REPAIRS

Through damage -
 6 new Iron Stanchions to Bulwarks. - Angle bars to Waterways recanted
 1 new Gig. & Poop cabins refitted

Periodical Survey

Keeling lifted from bilge to keelson on each side except two strakes
 Cement coating good & now extended to bilge. outside cleaned and
 coated. 2 new Hawseers

Present Condition of the

Decks	} Good	Treenails	} Good	Windlass and Capstan	} Good
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	} where	Timbers of the Frame at the opening	} where	Masts, Yards, &c.	} Afloat
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes	} Seen	Clamps and Shelves	} Seen	Anchors No. of	} Sufft
Topsides		Ceiling		Cables	
Wales		Rudder		Hawseers and Warps	
Plank (Bottom) and Counter		Copper cement When put on <u>1st 64th 68</u>		Standing & Running Rigging	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good

She is now in good condition and in my opinion
 may be classed A 1 and marked S. S. No 1. 68

Wm. C. Davey

The Amount of Fee.....£ : : : is received by me,

Mar 11 Special.....2 : 2 : — 16/68 JWM

Certificate (if required) : : : :

Committee's Minute Liverpool, 17th March, 1868

Character assigned A 1 S. S. No 1. 68

Special or Damage L 4-4-0 1/2/68



© 2019

Lloyd's Register
 Foundation

IRON 442-0053

"Hannula Mitchell"
- 21150 -



© 2019

Lloyd's Register
Foundation