

6086
ANNUAL SURVEYS.

✓ No. 9256 Survey held at Sunderland Date February 21st 18 68
 on the Iron Screw S^r "Ludworth" Master Meldrum
 No. in Reg. 88 Tonnage 445 Built at Glasgow When built 1866
 By whom built Mess^{rs} "Mingate" Owners London & N. Col. Coal Co. (Lim.)
 Port belonging to London Destined Voyage Coasting
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 4782 Port of Morpeth Classified A 1
 6, 66

The present Condition of the

Decks <u>Good</u>	Treenails <u>Keels</u>	Good when surveyed	Patent Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>		Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>		Boats <u>2 in keel</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>		Masts, Yards, &c. <u>Good when surveyed</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>		Sails <u>None found</u>
Plank sheers <u>"</u>	Keelsons <u>"</u>		Anchors No. of <u>3 B. 15. 16</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>		Cables <u>Complete</u>
Topsides <u>"</u>	Ceiling <u>"</u>		Hawsers and Warps <u>Good as appeared</u>
Wales <u>"</u>	Rudder <u>"</u>		Standing & Running Rigging <u>Good when surveyed</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>"</u>	When put on <u>"</u>	
General Observations and Opinion,		Caulking of Bottom, Deck, and Waterways <u>Good when surveyed</u>	

This vessel is in good condition and eligible, in my opinion, to remain as classed A 1

Committee's Minute 13th March 18 68

Character assigned A 1 was

© 2019
 Lloyd's Register
 Foundation

Certificate (if required).

IRON 442-0056