

60887 27031
Completion of No 1 Survey
REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 831 Survey held at London Date March 4th 18 68
on the Iron 13K "Merle" Master W. E. Pike
Tonnage 281 built at London When built 1863
By whom built Westwood Owners Scrutton & Co.
Port belonging to London Destined Voyage West Indies
If Surveyed Afloat or in Dry Dock Union Dry Dock

Last Survey, No. 5723 Port Iron. Classed A.1.
REPAIRS now done, 8.67

The bottom scraped and payed with
Coal tar and line —

Present Condition of the

Decks	} good	Transoms Rivets	} good	Windlass and Capstan	} good
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} where	Ditto Ditto at other places	} where	Condition, how ascertained	} by insp ⁿ & insp ^r
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales	} seen	Rudder	} seen	Hawsers and Warps	} efficient
Plank (Bottom) and Counter		Copper Coal Tar When put on <u>now</u>		Standing & Running Rigging	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where seen

The No 1 Survey having been now completed
(Please see Mr Keen's Report No 5723) She is
fit in my opinion to remain as classed A.1.
and to be marked in the Register Book (No. 67)
The Amount of Fee.....£ — : — : is received by me,

Special..... 1 : 1 :

Certificate (if required) : :

Committee's Minute 13th March 18 68

Character assigned A.1.
S.S. No. 1. 67 W. E. Pike



Lloyd's Register
Foundation

IRON442-0058