

6116
Iron

ANNUAL SURVEYS.

27063

No. 5224 Survey held at London Date March 26th 18 68
 on the S. B. Benvenue Master Whirhead
 Tonnage 999 Built at Glasgow When built 1867
 By whom built Barelay Owners Watson
 Port belonging to Glasgow Destined Voyage Port Philip
 If Surveyed Afloat or in Dry Dock on Pontoon Victoria Dock

Last Survey, No. 5224 Port of Iron Classed A 1
 The present Condition of the
 Decks where seen Good Treennails Rivets where seen Good Windlass and Capstan Good
 Waterways " Breasthooks and Stemson " Pumps "
 Comings " Transoms, Pointers, and Crutches " Boats "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Masts, Yards, &c. "
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Sails "
 Planksheers " Keelsons " Anchors No. of 3 B, 1 S, 2 K
 Sheerstrakes " Clamps and Shelves " Cables "
 Topsides " Ceiling " Hawsters and Warps "
 Wales " Rudder " Standing & Running Rigging "
 Plank (Bottom) and Counter " Copper " When put on "
 General Observations and Opinion, Caulking of Bottom, Deck, and Waterways where seen Good

Is now in good and efficient condition and in my opinion eligible to remain as classed.

Committee's Minute 24th March 1868
 Character assigned A 1

John Maxwell

Certificate (if required)

No. 202 Survey held at London Date March 19th 18 68
 on the S. S. Thomas Lea Master Bradley
 Tonnage 630 Built at Newcastle When built 1864
 By whom built Palmer Owners Lory & Co
 Port belonging to London Destined Voyage Coasting
 If Surveyed Afloat or in Dry Dock on Pontoon Victoria Dock

Last Survey, No. 5457 Port of Iron Classed C 1
 The present Condition of the
 Decks where seen Good Treennails Rivets where seen Good Windlass and Capstan Good
 Waterways " Breasthooks and Stemson " Pumps "
 Comings " Transoms, Pointers, and Crutches " Boats "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Masts, Yards, &c. "
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Sails "
 Planksheers " Keelsons " Anchors No. of 3 B, 1 S, 2 K
 Sheerstrakes " Clamps and Shelves " Cables "
 Topsides " Ceiling " Hawsters and Warps "
 Wales " Rudder " Standing & Running Rigging "
 Plank (Bottom) and Counter " Copper " When put on "
 General Observations and Opinion, Caulking of Bottom, Deck, and Waterways where seen Good

Is now in good and efficient condition and in my opinion eligible to remain as classed.

Committee's Minute 24th March 1868
 Character assigned A 1

John Maxwell
 Lloyd's Register
 Certificate (if required).

IRON442-0086