

# ANNUAL SURVEYS.

No. 21171 Survey held at Liverpool Date Feb 11 to March 11 1868  
 on the Iron-Ship "Trinidad" Master Larringa  
 Tonnage 674 Built at Tunderland When built 1866 - 8 mo  
 By whom built Dorford Owners Clano & Co  
 Port belonging to Liverpool Destined Voyage Manilla  
 If Surveyed Afloat or in Dry Dock Canning Graving & Salt House dock

Last Survey, No. 5169 Port of Liverpool Classed A 1

The present Condition of the

Decks	<u>Reels</u>	Windlass and Capstan <u>Good &amp; efficient</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	<u>Copper</u> <u>good</u> When put on <u>1866</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Satisfactory

The bottom scraped & coated with Composition. Is now in an efficient condition & in my opinion eligible to remain as Classed.

Committee's Minute Liverpool 31 March 1868

Character assigned

A 1 - Class 66 - S

J. B. Wheeler

Certificate (if required).

No. 166 Survey held at Liverpool Date March 2 to 26 1868  
 on the Iron-Ship "Knowsley" Master Robertson  
 Tonnage 647 Built at Pallion When built 1864 - 10 mo  
 By whom built Orvala Owners Shallcross & Co  
 Port belonging to Liverpool Destined Voyage San Francisco  
 If Surveyed Afloat or in Dry Dock Canning Graving & Salt House dock

Last Survey, No. 5353 Port of Liverpool Classed A 1

The present Condition of the

Decks	<u>Reels</u>	Windlass and Capstan <u>Good &amp; efficient</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	<u>Copper</u> <u>good</u> When put on <u>1864</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Satisfactory

The bottom scraped & coated with Composition. Is now in an efficient condition & in my opinion eligible to remain as Classed.

Committee's Minute Liverpool 31 March 1868

Character assigned

A 1 - Class 66 - S

J. B. Wheeler

Certificate (if required).

IRON442-0099



"Trinidad"  
-21171-  
"Knausley"



© 2019

Lloyd's Register  
Foundation