

6173
Iron.

29123

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** Survey held at London Date April 9th 6²³ 18⁶⁸
 on the Iron Ship "Carnarvon Castle" Master W. Pole.
 Tonnage 1200 built at Glasgow When built 1867. (6 mo.)
 By whom built Barclay Owners Currie and Co
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Wigram's dry Dock and East India St^{rs}

Last Survey, No. 5625 Port Iron. Classed A. 1. (Y. 67.)

REPAIRS Now done.

Sighted bottom, scraped, and payed with two coats of brown and one of Mc Innis's patent paints: the topsides painted.

Lifted some of the hatches in the hold and found the frames, &c., and Cement in good condition

Present Condition of the

Decks	<u>good</u> <u>where</u> <u>seen</u>	Trunks <u>Rivets</u>	<u>good</u> <u>where</u> <u>seen</u>	Windlass and Capstan	<u>good</u> <u>and</u> <u>sufficient</u> <u>where</u> <u>seen</u>
Waterways		Breasthooks and Stemson		Pumps <u>2 M. J. 1 Inc</u>	
Comings		Transoms, Pointers, and Crutches		Boats <u>4</u>	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c. <u>good</u>	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained <u>inspⁿ and augur^y</u>	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of <u>3 B. 15. 2 M.</u>	
Topsides		Ceiling		Cables	
Wales		Rudder <u>good</u>		Hawsers and Warps	
Plank (Bottom) and Counter		Copper <u>paint</u> When put on <u>now</u>		Standing & Running Rigging	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>Good where seen.</u>				

She is now in good and efficient condition and fit in my opinion to remain Classed A. 1.

The Amount of Fee.....£ : : is received by me,

Special.....

Certificate (if required) : :

Committee's Minute 28th April 18 68

Character assigned A 1 MMS.



© 2019
Lloyd's Register
Foundation
IRON442-0144