

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 10507** Survey held at Santh Shields Date 21 March 18 68
 403 on the Iron Steamer "Athena" Master R. Stodge
 Tonnage 1903 built at Santh Shields When built 1856
 By whom built Redhead & Co Owners Stodge & Co
 Port belonging to Santh Shields Destined Voyage Battle
 Surveyed Afloat or in Dry Dock at Santh

Last Survey, No. 5713 Port Iron Classed A 1
 8. 67.

REPAIRS

of damage to
 Scraped the bottom plating, Put on two coats of
 black paint, and two of black lead
 in main mast, top mast, top gallant mast - yards and
 rigging sheets new, some new sails
 two new boats

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper	Standing & Running Rigging

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways.

This vessel is now in good and efficient condition, and eligible to be continued as classed.

The Amount of Fee.....£ : : is received by me,

Special..... : 10: 6

Certificate (if required) : : :

Committee's Minute 12 May 18 68

Character assigned A 1



© 2019

Lloyd's Register
Foundation

IRON442-0181