

6263
Iron Ship
ANNUAL SURVEYS.

No. 110 Survey held at London Date May 23rd 1868
 on the Iron S.S. "New Pelton" Master F Page
 Tonnage 630 Built at Newcastle When built 1865
 By whom built _____ Owners J & E Joicey
 Port belonging to Newcastle Destined Voyage Coaster
 If Surveyed Afloat or in Dry Dock Lincolns Dry Dock

Last Survey, No. 5657 Port of Iron Classed A. 1
 (SS. No. 67)

The present Condition of the

Decks <u>good</u>	Treenails <u>Rivets</u>	<u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>4</u>	Breasthooks and Stemson _____		Pumps _____
Comings <u>4</u>	Transoms, Pointers, and Crutches _____		Boats _____
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame at the Openings _____		Masts, Yards, &c. _____
Lower Deck Beams & Fastenings <u>firm</u>	Ditto ditto at other places <u>where</u>		Sails _____ and _____
Planksheers <u>Painted</u>	Keelsons _____		Anchors No. of _____
Sheerstrakes <u>Painted</u>	Clamps and Shelves _____		Cables _____
Topsides <u>Painted</u>	Ceiling <u>seen</u>		Hawsers and Warps <u>efficient</u>
Wales <u>Painted</u>	Rudder _____		Standing & Running Rigging _____
Plank (Bottom) and Counter <u>Scraped Painted</u>	Copper <u>Asp.</u> When put on <u>65</u>		

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where seen
 Now done, the outside surface of the plating scraped and painted a few butts of the bottom plating caulked and a few rivets, about 18 renewed. She is now in good condition, fit in my opinion to remain as classed A. 1.
 Committee's Minute 2nd June 1868
 Character assigned A 1 MS

Certificate (if required)

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors No. of _____
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18____

Character assigned _____



© 2019

Lloyd's Register Foundation
 Certificate (if required)

IRON 442-0232