

6285

27345

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 378 Survey held at London Date May 19th June 1868
 on the Iron Ship "John C. Munro" Master J. Bannister
 Tonnage 612 built at Sunderland When built 1862
 By whom built _____ Owners Munro & Co.
 Port belonging to London Destined Voyage Nanagawa
 If Surveyed Afloat or in Dry Dock Union Dry Dock & East India Dock
 Last Survey, No. 5464 Port Iron. Classed A. 1
 (S.S. not by)

REPAIRS

now done,

The bottom scraped and painted with two coats of Zinc and one of Zinc and Tallow

Present Condition of the

Decks <u>good</u>	Freemails <u>Rivets</u> <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>good</u>	Breasthooks and Stemson <u>good</u>	Pumps <u>good</u>
Comings <u>good</u>	Transoms, Pointers, and Crutches <u>good</u>	Boats <u>and</u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame at the openings <u>good</u>	Masts, Yards, &c. <u>efficient</u>
Lower Deck Beams & Fastenings <u>where</u>	Ditto Ditto at other places <u>where</u>	Condition, how ascertained <u>by inquiry & inspection</u>
Planksheers <u>painted</u>	Keelsons <u>good</u>	Sails <u>good</u>
Sheerstrakes <u>do</u>	Clamps and Shelves <u>good</u>	Anchors No. of <u>3 B 1 S 2 W</u>
Topsides <u>do</u> <u>seen</u>	Ceiling <u>seen</u>	Cables <u>X</u>
Wales <u>do</u>	Rudder <u>seen</u>	Hawsers and Warps <u>sufficient</u>
Plank (Bottom) and Counter <u>painted</u>	Copper <u>Paint</u> When put on <u>now</u>	Standing & Running Rigging <u>good</u>

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. good where seen

She is now in good condition, fit in my opinion to remain as classed A. 1.

The Amount of Fee.....£ : : is received by me.

Special..... : :

Certificate (if required) : :

Committee's Minute 12th June 1868.

Character assigned A 1 MAS



© 2019

Lloyd's Register Foundation

IRON 1442-0253