

ANNUAL SURVEYS.

Recd. 22/6/68

Survey No. 3839 Survey held at Hull Date 10th June 18 68
 on the Iron Steamer Brownlow Master Rutter
 Tonnage 1086 Built at Hull When built 1867
 By whom built Edw Earle Owners Brownlow & Co
 Port belonging to Hull Destined Voyage St. Petersburg
 If Surveyed Afloat or in Dry Dock on No. 2 slip-way

Last Survey, No. 5694 Port of Iron.

Classed B 1
8.67

The present Condition of the

Decks	<u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>Good</u>	Breasthooks and Stemson	Pumps	<u>Good</u>
Comings	<u>Good</u>	Transoms, Pointers, and Crutches	Boats	<u>Good</u>
Upper Deck Beams & Fastenings	<u>Good</u>	Timbers of the Frame at the Openings	Masts, Yards, &c.	<u>Good</u>
Lower Deck Beams & Fastenings	<u>Good</u>	Ditto ditto at other places	Sails	<u>Good</u>
Planksheers	<u>Good</u>	Keelsons	Anchors No. of	<u>Good</u>
Sheerstrakes	<u>Good</u>	Clamps and Shelves	Cables	<u>Good</u>
Topsides	<u>Good</u>	Ceiling	Hawsers and Warps	<u>Good</u>
Wales	<u>Good</u>	Rudder	Standing & Running Rigging	<u>Good</u>
Plank (Bottom) and Counter	<u>Good</u>	Copper		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

Bottom cleaned & coated with Tar & black lead - Poop deck Caulked
Is slight in my opinion & remains as classed B 1

Committee's Minute 23rd June 18 68

Character assigned B 1

M. Davidson

Certificate (if required).

Survey No. 246 Survey held at Hull Date 17th June 18 68
 on the Iron Steamer Thyra Master Harboe
 Tonnage 552 Built at Newcastle When built 1866
 By whom built 444 Leslie Owners Anglo Danish Co
 Port belonging to Copenhagen Destined Voyage Copenhagen
 If Surveyed Afloat or in Dry Dock on No. No. 1 Slip-way & afloat in Prince's Dock

Last Survey, No. 6002 Port of Iron.

Classed B 1
2.67

The present Condition of the

Decks	<u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>Good</u>	Breasthooks and Stemson	Pumps	<u>Good</u>
Comings	<u>Good</u>	Transoms, Pointers, and Crutches	Boats	<u>Good</u>
Upper Deck Beams & Fastenings	<u>Good</u>	Timbers of the Frame at the Openings	Masts, Yards, &c.	<u>Good</u>
Lower Deck Beams & Fastenings	<u>Good</u>	Ditto ditto at other places	Sails	<u>Good</u>
Planksheers	<u>Good</u>	Keelsons	Anchors No. of	<u>Good</u>
Sheerstrakes	<u>Good</u>	Clamps and Shelves	Cables	<u>Good</u>
Topsides	<u>Good</u>	Ceiling	Hawsers and Warps	<u>Good</u>
Wales	<u>Good</u>	Rudder	Standing & Running Rigging	<u>Good</u>
Plank (Bottom) and Counter	<u>Good</u>	Copper		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

Bottom cleaned & coated with Paint - Ceiling Caulked
Is slight in my opinion & remains as classed B 1

Committee's Minute 23rd June 18 68

Character assigned B 1

M. Davidson

Certificate (if required).

IRON 442-0267