

# 6324 Iron Ships ANNUAL SURVEYS.

2938

No. 224 on the Iron Ship "Sarah & Emma" Master Sinclair  
 Survey held at London Date June 3<sup>rd</sup> 4<sup>th</sup> 1868  
 Tonnage 1097 Built at Liverpool When built 1860  
 By whom built Vernon Owners Farnworth  
 Port belonging to Liverpool Destined Voyage Liverpool  
 If Surveyed Afloat or in Dry Dock Ratcliff Dry Dock

Last Survey, No. 4756 Port of Iron. Classed A.1. (S.S. No. 64)

The present Condition of the

Decks	good	Transoms	good	Windlass and Capstan	
Waterways	✓	Breasthooks and Stemson		Pumps	good
Comings	✓	Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	fine	Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	✓	Ditto ditto at other places	where	Sails	
Planksheers	nailed	Keelsons		Anchors No. of 3B 1S 2K	and
Sheerstrakes	dr	Clamps and Shelves		Cables	
Upsides	dr	Ceiling	seen	Hawsers and Warps	efficient
Sides	dr	Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter	nailed	Copper Paint When put on	now		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

As it is nearly four years since she was specially surveyed & recommended Survey No 2 to be complied with now, but the ship has been moved from the Dry Dock without its being attended to. Now done, the bottom scraped & painted, she is now where seen in good condition. fit in my opinion to remain as classed A.1.

Committee's Minute

Character assigned

A.1 W.A.S.

H. J. Smith  
Certificate (if required)

No. 66 on the Iron Ship "Saint Leonards" Master G. Franklin  
 Survey held at London Date June 17<sup>th</sup> 22<sup>nd</sup> 1868  
 Tonnage 999 Built at Sunderland When built 1864  
 By whom built Pile Owners Bonus & B  
 Port belonging to London Destined Voyage  
 If Surveyed Afloat or in Dry Dock Union Dry Dock

Last Survey, No. 5572 Port of Iron. Classed A.1. 6, 67

present Condition of the

Decks	good	Transoms	good	Windlass and Capstan	good
Waterways	✓	Breasthooks and Stemson		Pumps	
Comings	✓	Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	fine	Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	✓	Ditto ditto at other places	where	Sails	and
Planksheers	nailed	Keelsons		Anchors No. of 3B 1S 2K	
Sheerstrakes	dr	Clamps and Shelves		Cables	
Upsides	dr	Ceiling	seen	Hawsers and Warps	efficient
Sides	dr	Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter	nailed	Copper Paint When put on	now		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

The Owners through the Captain declined to be surveyed in accordance with No 1 Survey at present as the flat is covered with coal. She is where seen in good condition. fit in my opinion to remain as classed A.1.

Committee's Minute

Character assigned

A.1 W.A.S.

H. J. Smith  
Certificate (if required).

180442-0289





Lloyd's Register  
Foundation