

ANNUAL SURVEYS.

6340

Rec 13/7/68
18 68

No. 5420 Survey held at Greenock Date 12th May
on the Iron Screw Steamer "Black Boy" Master John Campbell
Tonnage 16 gross Built at Greenock When built 1857
By whom built John Scott & Sons Owners Curtis & Co.
Port belonging to London Destined Voyage Glyde, Beaster
If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 5539 Port of Iron. 1867 Classed El. (S.S. No. 66)
6 months 67

The present Condition of the

Decks	<u>Where seen Good</u>	Treenails	<u>Rivets</u>	<u>Where seen Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>do do</u>	Breasthooks and Stemson	<u>do do</u>	<u>do do</u>	Pumps	<u>do</u>
Comings	<u>do do</u>	Transoms, Pointers, and Crutches	<u>do do</u>	<u>do do</u>	Boats	<u>do</u>
Upper Deck Beams & Fastenings	<u>do do</u>	Timbers of the Frame at the Openings	<u>do do</u>	<u>do do</u>	Masts, Yards, &c.	<u>do</u>
Lower Deck Beams & Fastenings	<u>do do</u>	Ditto ditto at other places	<u>do do</u>	<u>do do</u>	Sails	<u>Well found</u>
Planksheers	<u>do do</u>	Keelsons	<u>do do</u>	<u>do do</u>	Anchors No. of <u>2 Benders 1 Stream</u>	
Sheerstrakes	<u>Plating do do</u>	Clamps and Shelves	<u>do do</u>	<u>do do</u>	Cables	<u>Complete</u>
Topsides	<u>do do do</u>	Ceiling	<u>do do</u>	<u>do do</u>	Hawsers and Warps	<u>Sufficient</u>
Wales	<u>do do do</u>	Rudder	<u>do do</u>	<u>do do</u>	Standing & Running Rigging	<u>Good</u>
Plank (Bottom) and Counter	<u>do do do</u>	Copper	<u>When put on</u>	<u>do do</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

Vessel afloat, good where seen, I am of opinion this vessel is eligible to remain as classed.
Report detained in consequence of fee not having been paid.

Committee's Minute

14th July 18 68

Character assigned

B WAS

Joseph. P. M. W.

See to S.S. = July WNC
Certificate (if required).

No. _____ Survey held at _____ Date _____ 18 ____
on the _____ Master _____
Tonnage _____ Built at _____ When built _____
By whom built _____ Owners _____
Port belonging to _____ Destined Voyage _____
If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper	
	When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways _____

Committee's Minute

18

Character assigned



© 2019

Lloyd's Register
Certificate (if required).

IRON 442-0306