

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 12 Survey held at London Date July 3rd 18 60
 on the S. S. Galicia Master Straghan
 Tonnage 750 built at Hartlepool When built 1866
 By whom built Richardson Owners J. Hall Jun^r & Co
 Port belonging to London Destined Voyage Lady
 If Surveyed Afloat or in Dry Dock in Union Dock

Last Survey, No. 3640 Port Imm. Classed B 1
D. 67

REPAIRS

Scraped and painted bottom with two coats of red lead paint.

Present Condition of the

Decks <u>where seen Good</u>	Tronails <u>Rivets where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>from enquiry & as seen from deck</u>
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>213, 13, 2 K</u>
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>✓</u> When put on <u>✓</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>where seen Good</u>	

Is now in good and efficient condition and in my opinion eligible to remain as classed.

The Amount of Fee.....£..... is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 7th July 18 60

Character assigned B 1 WAS



© 2019

Lloyd's Register
Foundation

IRON 442-0312