

16392
Iron.

29/152

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 143 Survey held at London Date 16th to 23rd July 18 68
 on the Iron Screw "Latona" Master John. T. H. Hawkins
 Tonnage 699 Built at Newcastle When built 1883 (8 Mo.)
 By whom built Palmer Owners London Shipping Company (Limited)
 Port belonging to London Destined Voyage Mediterranean
 If Surveyed Afloat or in Dry Dock Portoona Victoria dock.

Last Survey, No. 5157 Port Iron. Classed 9. A. 1.
 (E. S. 1886.) 11. 1886

REPAIRS

Now done:- Sighted the Bottom, and caulked a number of Bulbs of the Plating. - Scraped and painted the Bottom with two coats of Zinc-paint and one of Gallos. Caulked the flats of the Main and Roop. decks. -

Present Condition of the

| | | | | | |
|-----------------------------------|----------------|----------------------------------------------------------------|----------------|----------------------------------------------------------------|---------------------------|
| Decks | } <u>Good</u> | <u>Rivets</u> | } <u>Good</u> | Windlass and Capstan | } <u>Good where seen.</u> |
| Waterways | | <u>Ironails</u> | | Pumps <u>Three</u> | |
| Comings | } <u>where</u> | Breasthooks and Stems | } <u>where</u> | Boats <u>Four</u> | } <u>Good</u> |
| Upper Deck Beams & Fastenings | | Transoms, Pointers , and Gratches | | Masts, Yards, &c. | |
| Lower Deck Beams & Fastenings | } <u>seen.</u> | Timbers of the Frame at the openings | } <u>Good</u> | Condition, how ascertained <u>By enquiry & observation</u> | } <u>sufficient</u> |
| Planksheers | | Ditto Ditto at other places | | Sails | |
| Sheerstrakes | } <u>seen.</u> | Keelsons | } <u>Good</u> | Anchors No. of <u>3 B. 15. 2 K.</u> | } <u>sufficient</u> |
| Topsides | | Clamps and Shelves | | Cables | |
| Wales | } <u>seen.</u> | Ceiling | } <u>Good</u> | Hawsers and Warps | } <u>sufficient</u> |
| Plank (Bottom) and Counter | | Rudder | | Standing & Running Rigging | |
| General Observations and Opinion, | | <u>Copper</u> <u>Paint</u> When put on <u>Now</u> | | | |
| | | <u>and Gallos</u> | | | |
| | | Caulking of Bottom, Deck, & Waterways. <u>Good where seen.</u> | | | |

She is now in good and efficient condition, and fit, in my opinion, to remain classed: 9. A. 1.

The Amount of Fee.....£ : : is received by me,

Special..... / : / : 0

Certificate (if required) : : f

Committee's Minute 31st July 18 68

Character assigned 9 A 1 was



© 2019

Lloyd's Register
Foundation

IRON442-0359