

ANNUAL SURVEYS.

No. 10644 Survey held at North Shields Date 18 July 1868
 on the Wm. & A. Hunter Master J. C. Hunter
 Tonnage 464 Built at Newcastle When built 1865
 By whom built J. & A. Hunter Owners J. & A. Hunter
 Port belonging to Newcastle Destined Voyage Mediteranean
 If Surveyed Afloat or in Dry Dock Master J. & A. Hunter

Last Survey, No. 5786 Port of Newcastle Classed B 1
4, 67.

The present Condition of the

Decks	Keelsons	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Cleaned the bottom plating and repainted the same with one coat of Red Lead. - Is in good and efficient condition and fit for service to remain as classed.

Committee's Minute 11th August 1868

Character assigned B 1 was

Certificate (if required).

No. 10644 Survey held at North Shields Date 20 July 1868
 on the Wm. & A. Hunter Master Geo. Cawley
 Tonnage 464 Built at Newcastle When built 1865
 By whom built J. & A. Hunter Owners J. & A. Hunter
 Port belonging to London Destined Voyage Mediteranean
 If Surveyed Afloat or in Dry Dock Master J. & A. Hunter

Last Survey, No. 6141 Port of Newcastle Classed A 1
SS No 1 68 3, 60.

The present Condition of the

Decks	Keelsons	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Now done. Cleaned the bottom plating and repainted the same with Abbe's patent paint. - She appears to be in good and efficient condition, and fit for service, eligible to continue as classed.

Committee's Minute 11th August 1868

Character assigned A 1 was

Certificate (if required).

IRON 1442-0376