

6454
row

#29397

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** _____ Survey held at London. Date 3rd and 4th July 1868.
 on the Iron Screw "Omega" Master W. J. Marshall.
 Tonnage 886 built at Sunderland. When built 1864 (4 Mo.)
 By whom built Laing. Owners Howwood.
 Port belonging to London. Destined Voyage St Petersburg.
 If Surveyed Afloat or in Dry Dock Pontoon's Victoria dock.

Last Survey, No. 3600 Iron Port _____ Classed A. 1.
 5/64.

REPAIRS

I wrote to the Captain and Owner respectfully recommending that this vessel be submitted to the Survey No. 2, prescribed in the Iron Rules; - at the same time intimating that, "unless the Rules in this respect were complied with. it was probable. on the same being reported to the Committee, the Vessel's class would be expunged from the Register Book." The owner has declined to submit her to the required Survey.

J. Williamson.

Present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stenson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto Ditto at other places _____	Condition, how ascertained _____
Planksheers _____	Keelsons _____	Sails _____
Sheerstrakes _____	Clamps and Shelves _____	Anchors No. of _____
Topsides _____	Ceiling _____	Cables _____
Wales _____	Rudder _____	Hawsers and Warps _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	Standing & Running Rigging _____
General Observations and Opinion, _____	Caulking of Bottom, Deck, & Waterways. _____	

The Amount of Fee.....£ : : is received by me,
 Special..... : :
 Certificate (if required) : :

Committee's Minute _____ 18 _____
 Character assigned _____

