

Iron Ship 6679 ANNUAL SURVEYS.

29/10/8

Recd 24/10/8

No. 6679 Survey held at London Date Aug 10 to 14 1868
 on the Iron S.S. "James Joyce" Master Morrel
 Tonnage 695 Built at Newcastle When built 1863
 By whom built Palmer Owners J. Fenwick
 Port belonging to London Destined Voyage Newcastle
 If Surveyed Afloat or in Dry Dock Pontoons, Victoria Dock

Last Survey, No. 5666 Port of Iron Classed 6 A. 1.
 (t. s. 66) ⁶⁷

The present Condition of the

Waterways } good
 Comings } where
 Upper Deck Beams & Fastenings } seen
 Lower Deck Beams & Fastenings } firm
 Planksheers Painted good
 Sheerstrakes " where
 Topsides " seen
 Wales " seen
 Plank (Bottom) and Counter Painted

Treenails Rivets
 Breasthooks and Stemson } good
 Transoms, Pointers, and Crutches }
 Timbers of the Frame at the Openings }
 Ditto ditto at other places } where
 Keelsons }
 Clamps and Shelves }
 Ceiling } seen
 Rudder }
 Copper Asp When put on 1863

Windlass and Capstan
 Pumps } good
 Boats three
 Masts, Yards, &c. } and
 Sails }
 Anchors No. of 3 B. 1 S. 2 W.
 Cables } efficient
 Hawser and Warps }
 Standing & Running Rigging }

Caulking of Bottom, Deck, and Waterways good where seen

now done. A few butts of bottom plating caulked and about a dozen rivets in the bottom renewed, the outside scraped and painted with two coats of Red lead and one of tallow; all the iron work above the water ballast tanks in the fore and after holds, chipped, scraped and painted. She is now in good condition, fit in my opinion to remain

Committee's Minute 28th August 1868.

Character assigned

6 A. 1. WAS

Certificate (if required)

No. 6679 Survey held at London Date Aug 15 to 18 1868
 on the Iron S.S. "Good Hope" Master Spence
 Tonnage 1235 Built at Sunderland When built 1868
 By whom built Owners Safe of Good Hope Steam Shipping Co.
 Port belonging to London Destined Voyage Safe of Good Hope
 If Surveyed Afloat or in Dry Dock James Dry Dock & Victoria Dock

Last Survey, No. 6406 Port of Iron Classed A. 1.
Spar Deck ⁶⁸

The present Condition of the

Decks } good
 Waterways }
 Comings }
 Upper Deck Beams & Fastenings } where
 Lower Deck Beams & Fastenings }
 Planksheers } seen
 Sheerstrakes }
 Topsides }
 Wales }
 Plank (Bottom) and Counter Lighted

Treenails Rivets
 Breasthooks and Stemson } good
 Transoms, Pointers, and Crutches }
 Timbers of the Frame at the Openings }
 Ditto ditto at other places } where
 Keelsons }
 Clamps and Shelves }
 Ceiling } seen
 Rudder }
 Copper few When put on 1868

Windlass and Capstan
 Pumps } good
 Boats }
 Masts, Yards, &c. } where
 Sails }
 Anchors No. of }
 Cables } seen
 Hawser and Warps }
 Standing & Running Rigging }

Caulking of Bottom, Deck, and Waterways good where seen

now docked for the purpose of fitting a new screw shaft, the first one having broken on her passage to London. She is now where seen in good condition.

Committee's Minute 28th August 1868.

Character assigned

A. 1. WAS

Certificate (if required).

IRON 442 - 0447