

REPORT of SURVEY for REPAIRS.

No. in
Reg. Book.

No. 21444 Survey held at Liverpool Date 14th Sept 1868

on the iron ship "Emasperini" Master J. Casco

Tonnage 449 built at Belfast When built 1866 - 8 mo

By whom built Harland Owners Dr. J. Rockbank

Port belonging to Liverpool Destined Voyage India

If Surveyed Afloat or in Dry Dock Lucas's Docks and Afloat

Last Survey, No.

50913

Port

Iron

Classed

A1

REPAIRS

The whole of the ceiling in the flat of bottom together with the timber boards all fore and aft on each side removed the fore and after ends cleared out, and the Plating Rivet frames re. found in good condition. The Cement Coatings sound and good and adhering satisfactorily to the iron.

Inside from upper turn of Ripe to upper deck stringer plate including the stringer plate cleaned and painted.

Bottom coated with M. S. S. S. Composition.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

General Observations and Opinion,

Tree-nails

Breasthooks and Stems

Transoms, Porters, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper

Caulking of Bottom, Deck, & Waterways.

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Shown in good and efficient condition and in my opinion eligible to remain as Classed A1 and the mark S.S. No. 1. 68.

The Amount of Fee.....£ . . . is received by me,

Special.....£ : £ : — 14/9/68 J.M.C.

Certificate (if required) . . .

Committee's Minute Liverpool 11th Sept 1868

Character assigned A 1 - 15th Sept 1868

Com-66



© 2019

Lloyd's Register
Foundation

IRON443-0001

"Cenadassin"

-214444-



© 2019
Lloyd's Register
Foundation