

6545 Iron. *27/10/77*

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 114 Survey held at London Date Sept^r 19th 23rd 1868
 on the Iron B^o "Cape City" Master J. Davies
 Tonnage 422 built at Sunderland When built 1861 (9 mo.)
 By whom built Pile Jun^r Owners H. Ellis
 Port belonging to London Destined Voyage Cape of Good Hope
 If Surveyed Afloat or in Dry Dock Nelson Slipway

Last Survey, No. 6003 Port Iron. Classed 12. A. 1 (1.68.)
 REPAIRS Now done. (t.v. 68.)

Sighted bottom, scraped and payed with White Zinc and tallow, the topsides painted.

Ballast in the Hold, Cement could not be seen.

Present Condition of the

Decks	<i>Good where seen</i> <i>Seeu</i>	Keelsons Rivets	<i>Good where seen</i> <i>Seeu</i>	Windlass and Capstan	<i>Good and sufficient where seen</i> <i>Seeu</i>
Waterways		Breasthooks and Stemson		Pumps <u>2</u>	
Comings		Transoms, Pointers, and Crutches		Boats <u>3</u>	
Upper Deck Beams & Fastenings		Transoms of the Frame at the openings		Masts, Yards, &c. <u>good</u>	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained <u>inspⁿ and enquiry</u>	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of <u>3 B.K. 1/2</u>	
Topsides		Ceiling		Cables	
Wales		Rudder <u>the good</u>		Hawesers and Warps	
Plank (Bottom) and Counter		Copper <u>Paint</u> When put on <u>now</u>		Standing & Running Rigging	
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways. <u>Good where seen.</u>			

She is now in good and efficient condition and fit in my opinion to remain as Classed 12. A. 1.

The Amount of Fee.....£ : : is received by me,

Special.....

Certificate (if required) : :

Committee's Minute 25 September 1868

Character assigned 12 A 1



© 2019

Lloyd's Register Foundation

IRON443-0015