

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 10699** Survey held at North Shields Date 21st October 18 68
 on the Sho. of "H. & Foster" Master Thos. Glover
 Tonnage 494 built at North Shields When built 1845-1846
 By whom built J. & Co. Smith Owners Messrs. Scott & Co.
 Port belonging to Newcastle Destined Voyage France
 Surveyed Afloat or in Dry Dock Messrs. J. & Co. Smith

Last Survey, No. 5820 Port Iron Classed A 1. 10. 67.

REPAIRS done, Cleaned down the bottom plating, - Caulked ~~up~~ up a few weeping butts.

Repainted the bottom with two coats of Red lead.
 Stitches to bulkheads overhauled and repaired, - Deck planks examined and put in order.

Present Condition of the

Decks	Treenails <u>Reels</u>	Windlass and Capstan <u>Complete & good</u>
Waterways	Breasthooks and Stemson	Pumps <u>do</u>
Comings	Transoms, Pointers, and Crutches <u>good</u>	Boats <u>4/12</u> <u>do</u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame at the openings	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>do</u>
Planksheers <u>where</u>	Keelsons <u>where</u>	Sails <u>do</u>
Sheerstrakes <u>Plating</u>	Clamps and Shelves	Anchors No. of <u>do</u>
Topsides <u>seen</u>	Ceiling <u>seen</u>	Cables <u>seen & for use complete</u>
Wales	Rudder	Hawsers and Warps <u>Complete & good</u>
Plank (Bottom) and Counter	Copper <u>When put on</u>	Standing & Running Rigging <u>do</u>

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. apparently good

This vessel appears in good and efficient condition and eligible to remain as classed.

The Amount of Fee.....£ : : : is received by me,

Special..... / : / : "

Certificate (if required) " : " : "

Committee's Minute 30th October 18 68

Character assigned A / 1



© 2019

Lloyd's Register Foundation

IRON443-0128