

6665
Row:

29578

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 264 Survey held at London Date 2nd 6th Nov^r 1868
 on the Iron Ship "Albert Victor" Master T. J. Clarke
 Tonnage 1184 built at London When built 1884 (4. Mo.)
 By whom built Millwall Iron Works Owners Lidgett & Sons
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Thames dry dock

Last Survey, No. 6268 Port Iron Classed 12. A. 1.
 (C.S. 1884) 964.

REPAIRS

Now done:- Sighted the Bottom and scraped and painted it with four coats of Bristol-paint. - Rebusked the pintles to the Rudder and fitted a new deck-plate to it. - Enlarged the Main-hatchway on the Lower-deck.

Present Condition of the

Decks	Good	Rails	Good	Windlass and Capstan	Good
Waterways		Greenails		Pumps	
Comings	where	Breasthooks and Stenson	where	Boats	Good where seen.
Upper Deck Beams & Fastenings		Transoms, Pointers, and Crutches		as Life-boats.	
Lower Deck Beams & Fastenings	selu.	Timbers of the Frame at the openings	selu.	Masts, Yards, &c.	Sufficient.
Planksheers		Ditto Ditto at other places		Condition, how ascertained	
Sheerstrakes	selu.	Keelsons	selu.	Sails	Good
Topsides		Clamps and Shells		Anchors	
Wales	selu.	Ceiling	selu.	Cables	Sufficient.
Plank (Bottom) and Counter		Rudder		Hawsers and Warps	
General Observations and Opinion,		Copper		Standing & Running Rigging	
		When put on			
		1884			
		Caulking of Bottom, Deck, & Waterways.			

She is now in good and efficient condition, and fit, in my opinion, to be classed: A. 1. (C.S. no 1. 1884) as desired by the Owners, in lieu of "12. A. 1 (C.S. 1884)".

The Amount of Fee.....£ : : is received by me,

Special..... : : -

Certificate (if required) : :

Committee's Minute 10th November 1868

Character assigned A 1

S.S. no. 1-17



© 2019

Lloyd's Register

IRON443-0132