

# ANNUAL SURVEYS.

No. 166 Survey held at London Date Nov 7<sup>th</sup> to 13<sup>th</sup> 1868  
 on the Ship Leon Dulle Master Samuel Parry  
 Tonnage 1435 Built at Liverpool When built 1863  
 By whom built                      Owners Messrs J. A. Brown & Co  
 Port belonging to Liverpool Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock Messrs Wigram's Dry Dock & East India Dock

Last Survey, No. 5943 Port of Iron Classified A-1 12, 67  
SS No 1-1867

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

General Observations and Opinion,

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

Caulking of Bottom, Deck, and Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors

No. of 3B. 1S. 2H

Cables

Hawsers and Warps

Standing & Running Rigging

Scraped and painted  
Now done her bottom Scraped and Painted - She is now  
in good and efficient Condition, fit in my opinion to  
Remain as classed A-1.

Committee's Minute 24<sup>th</sup> November 1868

Character assigned

A-1

Certificate (if required)

No. 415 Survey held at London Date Nov 5<sup>th</sup> to 17<sup>th</sup> 1868  
 on the Ship Poslin Castle Master R Davidson  
 Tonnage 1170 Built at Glasgow When built 1863  
 By whom built Papier Owners Messrs Currie & Co  
 Port belonging to Liverpool Destined Voyage Melbourne  
 If Surveyed Afloat or in Dry Dock Messrs Wigram's Dry Dock & London Dock

Last Survey, No. 5998 Port of Iron Classified A-1 1. 1. 68  
SS No 1-68

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

General Observations and Opinion,

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

Caulking of Bottom, Deck, and Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors

No. of 3B. 1S. 2H

Cables

Hawsers and Warps

Standing & Running Rigging

Scraped and painted  
Her Bottom has been Scraped and Painted, and then Coated  
with Mc Innis' Composition - She is now in good and efficient  
Condition, fit in my opinion to remain as classed A-1.

Committee's Minute 24<sup>th</sup> November 1868

Character assigned

A-1

Certificate (if required)