

# REPORT of SURVEY for REPAIRS.

6814

Ru 25/1/69

No. in Reg. Book. **No.** 3454 Survey held at Grangemouth Date 13<sup>th</sup> January 1869  
207 on the Shon S.S. "Bertha" Master \_\_\_\_\_  
 Tonnage 341 built at Glasgow When built 1864  
 By whom built Wingate Owners Seligmann  
 Port belonging to Glasgow Destined Voyage France  
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 5939 Port Iron. Classed A. 1.  
(S.S. No. 1-64) 12-64.

## REPAIRS

*Now done, - Outside plating scraped clean, and re-coated with two coats of Paint.*

### Present Condition of the

Decks <u>In good condition</u>	Rivets <u>Good where seen</u>	Windlass and Capstan <u>L. W. Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>2</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>4</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frames at the openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto Ditto at other places <u>"</u>	Condition, how ascertained <u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Sails <u>A. 1.</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 B. 10. 2. 16</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Wales <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Plating (Bottom) and Counter <u>"</u>	Copper <u>When put on</u>	Standing & Running Rigging <u>"</u>

### General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tried.

*This vessel is in good and efficient condition. eligible in my opinion to remain as classed A. 1.*

The Amount of Fee.....£ 0 : 0 : 0 is received by me,

E. R. R. Special..... : :  
 Certificate (if required) : :

Edmund Couchman

Committee's Minute 26<sup>th</sup> January 1869

Character assigned B 1



© 2019

Lloyd's Register

IRON 443-0280