

6820

207737

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 724 Survey held at London Date 15th Jan'y 19th 1869
on the Iron Ship Star of Albion Master J. Smyth
Tonnage 1025 built at Belfast When built 1864
By whom built Harland Owners Corry & Co.
Port belonging to Belfast Destined Voyage India
If Surveyed Afloat or in Dry Dock Britannia dry dock

Last Survey, No.

6169

Port

Iron.

Classed

A. 1.

4.68

REPAIRS

Clean scraped the bottom. Lifted the timbers fore and aft both sides, and a shake of the lower hold ceiling, examined ribs, plates, rivets, Cement, &c. Recoated or payed the plates up to load line with two coats of oxide of iron. then with "McQuinn's" Patent composition. -

Present Condition of the

Decks	<u>good</u>	Freeboards	<u>Rivets</u>	<u>good</u>	Windlass and Capstan	<u>in good order</u>
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	<u>from</u>	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained	<u>from the Dk &c</u>
Planksheers	"	Keelsons	"	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	"	Anchors No. of	<u>3</u>
Topsides	"	Ceiling	"	"	Cables	"
Wales	"	Rudder	<u>efficient</u>	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper	<u>When put on</u>	"	Standing & Running Rigging	"

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

Good

Surveyed her in accordance with the Rules No 1 Survey.
She is in my opinion fit for the conveyance of dry and perishable
Cargoes to and from all parts of the World

The Amount of Fee.....£

Special..... 2 : 2 :

Certificate (if required) : 5 :

is received by me, and entitled to remain as
Clas'd A. 1. and to be mark'd in
the Reg'r S. S. No 1.

Committee's Minute

22nd January 1869

Character assigned

A 1 S. S. No 1-69

Samuel Phipps



© 2019

Lloyd's Register
Foundation

IRON443-0286