

# ANNUAL SURVEYS.

No. 2173 Survey held at Liverpool Date Dec 9 to 28 1868  
 on the (Bon) S "Staffordshire" Master Potts  
 Tonnage 1173 Built at L'pool When built 1862 - 10 mo  
 By whom built Jones Owners Boult & Co  
 Port belonging to L'pool Destined Voyage India  
 If Surveyed Afloat or in Dry Dock Clarence Graving & Wellington Dock

Last Survey, No. 5055 Port of Iron

Classed

A 1  
(S.S. 1-64) 66

The present Condition of the

Decks	Treenails <u>Pirets</u>	Windlass and Capstan <u>Good &amp; sufficient</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of <u>3 Bs - 15 &amp; 2 1/2</u>
Sheerstrakes	Clamps and Shelves	Cables <u>Good where seen</u>
Topsides	Ceiling	Hawsers and Warps <u>2 well found</u>
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Cement <u>Good</u> When put on <u>1862</u>	

General Observations and Opinion,

The Ceiling in flat of bottom lifted in places, all oxidation removed, the Hull inside coated with iron ore paint & outside with Composition & other paint - Is now in an efficient condition & in my opinion eligible to remain as Classed.

Committee's Minute Liverpool 9th March 1869

Character assigned

A 1 - Can 62

E. C. Wheeler

Certificate (if required).

No. 107 Survey held at Liverpool Date Feb 2 to March 2 1869  
 on the Sm S "Bedfordshire" Master F Morgan  
 Tonnage 1155 Built at L'pool When built 1863 - 8 mo  
 By whom built Potter Owners Boult & Co  
 Port belonging to L'pool Destined Voyage India  
 If Surveyed Afloat or in Dry Dock Sandon Graving & Dock

Last Survey, No. 5041 Port of Iron

Classed

A 1  
(S.S. 1-64) 66

The present Condition of the

Decks	Treenails <u>Pirets</u>	Windlass and Capstan <u>Good &amp; sufficient</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of <u>3 Bs - 15 &amp; 2 1/2</u>
Sheerstrakes	Clamps and Shelves	Cables <u>Good where seen</u>
Topsides	Ceiling	Hawsers and Warps <u>2 well found</u>
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Cement <u>Good</u> When put on <u>1863</u>	

General Observations and Opinion,

The Bottom scraped & coated with Composition. Is now in an efficient condition & in my opinion eligible to remain as Classed.

Committee's Minute Liverpool 9th March 1869

Character assigned

A 1 - Can 63

E. C. Wheeler

Certificate (if required).

IRON 443-0380



Staffordshire  
-21.7.39-  
Bedfordshire



© 2019

Lloyd's Register  
Foundation