

REPORT of SURVEY for REPAIRS.

No. in Reg. Book 166 No. 21741 Survey held at Birkenhead Date 1 to 23rd Mar 1869
 on the Iron Bk "Recife" Master Blandford
 Tonnage 465 built at Belfast When built 1862 - 10 mo
 By whom built Harland Owners J Rapier
 Port belonging to Liverpool Destined Voyage Lima
 If Surveyed Afloat or in Dry Dock Clover's dry dock & Afloat

Last Survey, No. 5663 Port Iron Classed 12 A 1
t.s. 66 7

REPAIRS

Periodical Survey No 2

Ceiling equal to three strakes all fore and aft on both sides, the cement coating &c examined and where necessary the cement repaired. Plow plates cement washed, bottom cleaned and coated.

Present Condition of the

Decks	} Good and firm where seen	Ironails	Rivets	Good	Windlass and Capstan	} Good and efficient where seen
Waterways		Breasthooks and Stems	"	"	Pumps	
Comings		Transoms, Pointers, and Crutches	"	"	Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings	where	"	Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places	"	"	Condition, how ascertained	
Planksheers		Keelsons	"	"	Sails	
Sheerstrakes		Clamps and Shells	seen	"	Anchors No. of	
Topsides		Ceiling	"	"	Cables	
Wales		Rudder	"	"	Hawsers and Warps	
Plank (Bottom) and Counter		Copper	Cement	When put on 1862	Standing & Running Rigging	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good

She is now in good condition and in my opinion may continue as classed and marked t.s. 69

The Amount of Fee.....£ : : is received by me,

Special.....2 : 2 : - 29/3/69

Certificate (if required) " : 5 : "

Committee's Minute Liverpool 30th March 1869

Character assigned 12 A 1 - (t.s. 69)



© 2019

Lloyd's Register Foundation

IRON 444-0006

1811 1812 1813 1814 1815 1816 1817 1818 1819 1820

Deeds



© 2019

Lloyd's Register
Foundation