

# ANNUAL SURVEYS.

No. 156 Survey held at London Date 22<sup>nd</sup> April 18 69  
 on the Iron Ship "Wright's Grant" Master  
 Tonnage 1312 Built at Gull When built 1858  
 By whom built ✓ Owners 2<sup>d</sup> Carlyle  
 Port belonging to Birkenhead Destined Voyage London to  
 If Surveyed Afloat or in Dry Dock Thames Dry Dock

Last Survey, No. 6286 Port of Iron. Classed AI SS No 1-68  
 6 68

The present Condition of the

Decks	<u>Good when seen</u>	Treenails	<u>Good when seen</u>	Windlass and Capstan	<u>good</u>
Waterways		Breasthooks and Stemson		Pumps	<u>"</u>
Comings		Transoms, Pointers, and Crutches		Boats	<u>"</u>
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	<u>See from deck good</u>
Lower Deck Beams & Fastenings		Ditto ditto at other places		Sails	<u>Sufficient</u>
Planksheers		Keelsons		Anchors No. of	<u>3 B. 1 S. 2 H.</u>
Sheerstrakes		Clamps and Shelves		Cables	<u>Sufficient</u>
Topsides		Ceiling		Hawsers and Warps	<u>good &amp; Sufficient</u>
Wales		Rudder		Standing & Running Rigging	<u>good</u>
Plank (Bottom) and Counter		Copper		When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good when seen

Bottom scraped and painted with two coats of Zinc and one coat of Tallow. Is now in good order and condition and eligible in my opinion to remain as classed AI SS No 1-68

Committee's Minute 30<sup>th</sup> April 18 69

Character assigned A 1 WAS

Joseph J. Tucker

Certificate (if required)

No. 44 Survey held at London Date 22<sup>nd</sup> April 18 69  
 on the Iron Ship "Pandora" Master E. Ankers  
 Tonnage 1156 Built at Glasgow When built 1864  
 By whom built Cornwall Owners Moore & Co  
 Port belonging to Liverpool Destined Voyage London to  
 If Surveyed Afloat or in Dry Dock Migrams Dry Dock

Last Survey, No. 6553 Port of Iron. Classed AI SS No 1-68  
 6 68

The present Condition of the

Decks	<u>Good when seen</u>	Treenails	<u>Good when seen</u>	Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	<u>good</u>
Comings		Transoms, Pointers, and Crutches		Boats	<u>"</u>
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	<u>See from deck good</u>
Lower Deck Beams & Fastenings		Ditto ditto at other places		Sails	<u>Sufficient</u>
Planksheers		Keelsons		Anchors No. of	<u>3 B. 1 S. 2 H.</u>
Sheerstrakes		Clamps and Shelves		Cables	<u>Sufficient</u>
Topsides		Ceiling		Hawsers and Warps	<u>good &amp; Sufficient</u>
Wales		Rudder		Standing & Running Rigging	<u>good</u>
Plank (Bottom) and Counter		Copper		When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good & Sufficient

Bottom scraped and painted with two coats of Zinc paint and one coat of Tallow. Is now in good order and condition and eligible in my opinion to remain as classed AI SS No 1-68

Committee's Minute 30<sup>th</sup> April 18 69

Character assigned A 1 WAS

Joseph J. Tucker

Certificate (if required)