

REPORT of SURVEY for REPAIRS.

7046

Rev 8/5/69

No. in Reg. Book. **No. 10839** Survey held at North Shields Date 8th April 1869
 on the S.S. "J. E. Forster" Master W. Robson
 Tonnage 694 built at North Shields When built 1866
 By whom built J. W. Smith Owners Scott & Co
 Port belonging to Newcastle Destined Voyage London
 If Surveyed Afloat or in Dry Dock In dry dock

Last Survey, No. 6661 Port Iron Classed 13 / 1
 10, 68.

REPAIRS

Both surfaces of outside plating exposed, and found satisfactory and painted with red lead.

The man-hole doors lifted, and double bottom examined and current repaired where necessary.

Present Condition of the

Decks		Treenails <u>Nails</u>		Windlass and Capstan	<u>Good</u>
Waterways		Breasthooks and Stemson		Pumps	<u>Good</u>
Comings		Transoms, Pointers, and Crutches		Boats	<u>3 in ke</u>
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings	<u>Good</u>	Masts, Yards, &c.	<u>Examined</u>
Lower Deck Beams & Fastenings	<u>Good</u>	Ditto Ditto at other places	<u>when</u>	Condition, how ascertained	<u>Examined when present</u>
Planksheers	<u>when</u>	Keelsons	<u>seen</u>	Sails	<u>Good</u>
Sheerstrakes	<u>seen</u>	Clamps and Shelves		Anchors No. of	<u>3 B. 1 S. 2 K.</u>
Topsides		Ceiling		Cables	<u>Complete</u>
Wales		Rudder		Hawsers and Warps	<u>Good</u>
Plating		Copper	<u>When put on</u>	Standing & Running Rigging	<u>Good when seen</u>
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good

The vessel is in good condition, and eligible, in my opinion, to remain as classed 13-1 and marked S.S. No. 69. in the Register book.

The Amount of Fee.....£ : : is received by me,

Special..... 2 : 2 : :

Certificate (if required) : : : :

Committee's Minute 4th May 1869

Character assigned B 1



© 2019

Lloyd's Register Foundation

IRON444-0093