

7181

3074

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 57 Survey held at London Date 16th June 1869
 on the Ship "Sarah Grace" Master M^r Green
 Tonnage 1071 built at Port Glasgow When built 1865 - 4 mo
 By whom built Wibb Owners Grace & Co
 Port belonging to London Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock London Dry Dock and Afloat.

Last Survey, No. 6179Port IronClassed A1

4.68

REPAIRS

Hold cleared the timber boards and ceiling equal to new, shake fore and aft on both sides removed. The frames, Plating, Rivets re found to be in good condition and the cement coating adhering satisfactorily to the iron.

Bottom cleaned and coated with McSparran's Composition

Present Condition of the

Decks
 Waterways
 Comings
 Upper Deck Beams & Fastenings
 Lower Deck Beams & Fastenings
 Planksheers
 Sheerstrakes
 Topsides
 Wales
 Plank (Bottom) and Counter

Rivets
 Breasthooks and Stemson
 Transoms, Pointers, and Crutches
 Timbers of the Frame at the openings
 Ditto Ditto at other places
 Keelsons
 Clamps and Shelves
 Ceiling
 Rudder
 Copper Cem When put on 1865

Windlass and Capstan Good
 Pumps —
 Boats —
 Masts, Yards, &c. —
 Condition, how ascertained seen from the deck
 Sails —
 Anchors No. of 3 Good
 Cables — and
 Hawser and Warps Sufficient
 Standing & Running Rigging —

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

Good where examined

Is now in good and efficient condition and in my opinion eligible to remain as Classed and to be marked 'S.S. No. 1-69'

The Amount of Fee.....£ — : — : is received by me,

Special..... 3 : 3 : —Certificate (if required) : 5 : —Committee's Minute 25th June 1869Character assigned A1S.S. No. 1-69 —

© 2019

Lloyd's Register Foundation

IRON 444-0227