

ANNUAL SURVEYS.

No. 21957 Survey held at Liverpool. Date 15 to 26 July 1869
 on the SHIP INDUS Master Lock
 Tonnage 966 Built at Dumbarton When built 1866 - 7 mo
 By whom built — Owners J. Rouse
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Brunswick by Lock and afloat.

Last Survey, No. 5559 Port of Iron. Classed A S. 6. 67.

The present Condition of the

Decks	Treenails <u>Reels.</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of <u>good & efficient</u>
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Cumant</u> When put on <u>1866.</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen.

Bottom scraped and painted. Iron Bone put repaired. She is now in good and efficient condition - and in my opinion is fit to remain as classed. A. S.

Committee's Minute Liverpool 3rd August 1869

Character assigned A S.

Certificate (if required).

No. 299 Survey held at Liverpool. Date 16 July to 2 August 1869
 on the SHIP "ALCATRAZ" Master H. Robinson
 Tonnage 843 Built at Liverpool When built 1868 - 5 mo.
 By whom built — Owners Mayers & Sons.
 Port belonging to Liverpool Destined Voyage San Francisco
 If Surveyed Afloat or in Dry Dock Brunswick by Lock and afloat.

Last Survey, No. 6442 Port of Iron. Classed A S. 7. 68.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of <u>good & efficient</u>
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Cumant</u> When put on <u>1868.</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen.

Bottom scraped and painted - she is now in good and efficient condition - and in my opinion, is fit to remain as classed. A. S.

Committee's Minute Liverpool 3rd August 1869

Character assigned A S.

Certificate (if required).

IRON 444-0302

ALPHABETIC SURVEY

"
Andrus
"

Alcatraz

21937



© 2019

Lloyd's Register
Foundation